

Portsmouth International Port – Local Notice to Mariners No. 03/17

Dated 26th April 2017

Derelict Quay Side - Danger to Navigation - Town Camber Entrance Portsmouth

1. **NOTICE IS HEREBY GIVEN** by the Harbour Master of Portsmouth International Port that the state of the quayside fendering arrangements on the southern side of the Town Camber Entrance are unstable and are deemed to be a danger to navigation.
2. All vessels are advised to give the damaged quayside fendering a wide berth in case there are any underwater obstructions in the vicinity.



Captain Rupert Taylor

Harbour Master

Portsmouth International Port